



## Thermax<sup>®</sup>

---

### Instructions for Use

---

**Product Description:** Irreversible Temperature Labels

---

**Standard Range:** 29-290°C / 84-554°F

**Directions:** Peel indicator from release paper

Apply to a clean, grease free surface ensuring that the indicator has adhered to the surface

A colour change from silver white / orange to black indicates that the rating has been reached.

**Storage:** Store in a cool dry place below 18°C (64°F)